GEEEK

Version 2.X

A50 PLUS INSTALLATION GUIDE

SCREWS LIST 螺絲列表

A

A1

A2

A1 Plastic Pad 墊片 x6
A2 Standoff 銅柱 x6

B

M4 Thumb Screw
M4手擰螺絲

C

Screws for Fan
風扇螺絲

D

Screws for PSU
電源螺絲

E

M3 T type Nut
M3螺母

F

M4x14mm

G

M4x8mm

H

M3x8mm

I

M3x5mm

J

M3x5mm

Aluminum Frame Installation 鋁框架安裝說明

**01**

Screw 螺絲

Acrylic Panel 壓克力板

Nut 螺母

02

03

04

⚠ Please read the "Aluminum Frame installation"before assembling this case
安裝前請務必先理解鋁框架如何安裝

STEP 01

Aluminum Frame Installation

安裝機身鋁框架

F 4X

STEP 02

HDD Bracket Installation

安裝硬碟支架到右側鋁框架

E 4X

H 4X

STEP 03

Back Panel Installation

安裝後面板

G 4X

G

STEP 04

Install the PSU Metal Bracket on the Front Panel

安裝電源鐵支架到前面板

J 3X

STEP 05

Install the (1)USB 3.0 Cable and (2)Power Switch on the front panel first, then install the (3)front panel on the case

安裝(1)雙USB 3.0線 及 (2)電源開關到前面板, 然後安裝(3)前面板

J 1X

H 4X

3

J

2

1

H

G

G 4X

STEP 06

Install the Standoff and Plastic Pad on the M/B Metal Bracket

安裝銅柱及墊片到主機板鐵支架

A
2

A
1

STEP 07

M/B Metal Bracket installation

安裝主機板鐵支架

J 3X

# STEP 08

M/B installation

安裝主機板

I

I 4X

STEP 09

Power Supply Installation

安裝電源供應器

D 4X

STEP 10

Power Extension Cable Installation

安裝電源延長線

J 2X

STEP 11

PCIe Riser Extension Cable Installation

安裝PCI-E延長線

STEP 12

GPU Card Installation

安裝顯示卡

I 1X

STEP 13

2.5" SSD/HDD Installation

安裝2.5"硬碟

G 4X

J 8X

G

J

STEP 14

Case Fan Installation on the Top Panel

安裝系統風扇到上面板

C 8X

C

# STEP 15

Top Panel Installation

安裝上面板

H

E

E 6X

H 6X

STEP 16

Case Fan and Bottom Panel Installation

安裝系統風扇(可選)及底蓋

J 2X

E 4X

H 4X

Please complete the cable management before installing the bottom panel.
請先完成所有的整線後再安裝底蓋

There are two sides for the bottom panel, one side with the countersunk holes needed to be toward to the outside.
底蓋有分正反面，沉孔的那一面朝外．

J

J

H

E

STEP 17

Footpad Installation on the Bottom Panel

安裝機殼腳墊到底蓋

J 4X

J

STEP 18

Side Panel Installation

安裝側板